

CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM		Page <u>1</u> of <u>2</u>
Sewershed: Dundalk	Consultant: RJN Group, Inc.	Date: YYYYMMDD <u>2008/10/16</u>
Test to be performed: Smoke <input type="checkbox"/> Dye <input checked="" type="checkbox"/>	Ground Condition: Dry <input checked="" type="checkbox"/> Damp <input type="checkbox"/> Wet <input type="checkbox"/>	Supervisor Initials: <u>TS</u>
Manhole ID: <u>S61K-010 MH</u>	Test ID: <u>D1047-026</u>	Notifications - made daily: <input checked="" type="checkbox"/> (Residents, Fire, 311)

Field Sketch: Show all manholes with numbers, blower placement location, sandbag or isolation device location, street names, building addresses and locations, defect locations and photograph numbers.

East Ave

5115

shed  
1  
2

Downspout/roof Drain  
5 minute - 10 Gallon  
Dye coming out in grass by sidewalk  
NO Dye observed in Sanitary

S61K-010 Hudson St S61K-021

CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM		Page <u>1</u> of <u>2</u>
Sewershed: Dundalk	Consultant: RJN Group, Inc.	Date: YYYYMMDD <u>2008/10/16</u>
Test to be performed: Smoke <u>  </u> Dye <u>✓</u>	Ground Condition: Dry <u>✓</u> Damp <u>  </u> Wet <u>  </u>	Supervisor Initials: <u>TS</u>
Manhole ID: <u>S61K-010 MH</u>	Test ID: <u>D1047-026</u>	Notifications - made daily: <u>✓</u> (Residents, Fire, 311)
Field Sketch: Show all manholes with numbers, blower placement location, sandbag or isolation device location, street names, building addresses and locations, defect locations and photograph numbers.		



D1047-026-OB01-P01



D1047-026-OB01-P02